



**Railway Accident  
Investigation Unit  
of Ireland**

**Annual Report**



**Annual Report 2013**

Report number: 2013-AR2013

Published: 25/09/2014

---

## Document History

Title	Annual Report 2013
Document type	Annual Report
Document number	2013-AR2013
Document issue date	

Revision number	Revision date	Summary of changes

---

## Foreword

The purpose of the Railway Accident Investigation Unit's is to independently investigate occurrences on Irish railways with a view to establishing their cause and make recommendations to prevent their recurrence or otherwise improve railway safety.

Forty one preliminary examinations were carried out in 2013, from which six full investigations were commenced. The first investigation involved a failure in single line working operations, the second investigation related to a reoccurring fault on the DART rolling stock, the third was the result of a fire on a LUAS tram, the fourth and fifth investigations related to structural collapses of a railway canopy at Cork and cutting at Waterford, respectively. The final investigation is a trend investigation into the Signals Passed at Danger (SPAD); this investigation was triggered by two incidents occurring on the 8<sup>th</sup> and 19<sup>th</sup> December 2013.

The Railway Accident Investigation Unit published three investigations reports in 2013 relating to two occurrences that took place in 2012 and one that took place in 2009. The 2009 investigation involved a collision between a tram and a bus at O'Connell Street in Dublin. The 2012 investigations included a collision between tractor and a train at a user worked level crossing and an unplanned initiation of fog signals which led to a train driver sustaining minor injuries. A total of seven new safety recommendations were issued in 2013. The focus of the safety recommendations were: the effective implementation of safety controls; improvements to competency management systems; and the management of risk at user worked level crossings.

Ninety seven safety recommendations have been issued in total up to the end of 2013, including fourteen issued by the Railway Safety Commission in advance of the appointment of a Chief Investigator for the Railway Accident Investigation Unit in 2007. The Railway Safety Commission monitors the implementation of safety recommendations and has advised that of the ninety seven safety recommendations issued to date, forty six have been closed out as having been addressed, twenty four are complete and awaiting verification that they have been addressed, and a further twenty seven are open.

A position for a Senior Investigator became vacant in October 2012, however the RAIU have not yet been given sanction to fill the post. This continues to be a concern and may cause a risk to the operational needs of the Unit.

David Murton  
Chief Investigator

---

## Contents

1	Background .....	1
2	RAIU .....	2
2.1	The organisation .....	2
2.2	Railway networks within the RAIU's remit.....	2
2.3	Non-investigative activities .....	4
3	Occurrences .....	5
3.1	Classification of occurrences .....	5
3.2	Investigation of occurrences .....	5
3.3	Summary of occurrences in 2012 .....	7
3.4	Investigations within the past five years.....	7
4	Investigations commenced in 2013.....	10
4.1	Irregularity during Single Line Working between Dundalk and Newry.....	10
4.2	Dart wrongside door failure at Salthill and Monkstown .....	10
4.3	Tram fire on approach to Busarás.....	11
4.4	Collapse of canopy at Cork Kent Station .....	11
4.5	Rockfall at Waterford station .....	12
4.6	Signal Passed at Danger (SPAD) occurrences on IÉ network .....	12
5	Investigation reports published in 2013 .....	14
5.1	Overview of investigation reports for 2013.....	14
5.2	Tram collision with a bus on O'Connell Street .....	14
5.3	Explosion on Dart at Bray Station .....	14
5.4	Tractor struck train at level crossing XE020 .....	16
6	Safety recommendations .....	18
6.1	Monitoring of RAIU safety recommendations .....	18
6.2	Progress in 2012 .....	18
6.3	Summary of status of recommendations .....	19
	Appendix – Status of individual recommendations by report – 2006.....	21
	Status of individual recommendations by report – 2008.....	22
	Status of individual recommendations by report – 2009.....	23
	Status of individual recommendations by report - 2010.....	24
	Status of individual recommendations by report - 2011.....	28
	Status of individual recommendations by report – 2012.....	32
	Status of individual recommendations by report – 2013.....	34

---

## List of abbreviations

---

ERA	European Railway Agency
HABD	Hot Axlebox Detector
IE	Iarnród Éireann
NIB	National Investigation Body
No.	Number
NSA	National Safety Authority
RAIU	Railway Accident Investigation Unit
RSC	Railway Safety Commission
SI	Statutory Instrument

## List of figures

---

Figure 1 – Organisation chart.....	2
Figure 2 – Investigation trend 2009-2013 .....	9
Figure 3 – Rolling stock used for cross border service on 23 <sup>rd</sup> March.....	10
Figure 4 Damaged to autocoupler .....	11
Figure 5 Fire on LUAS tram .....	11
Figure 6 Debris on train at Cork station .....	12
Figure 7 Landslide obstructing track .....	12
Figure 8 Tram collision with bus .....	14
Figure 9 Damage to driver bag and cabin.....	14
Figure 10 Damage to tractor .....	16
Figure 11 – Status of recommendations .....	20

## List of tables

---

Table 1 – Preliminary examination reports in 2012 by network .....	7
Table 2 – Full investigations within the past five years by type .....	8
Table 3 – Recommendation status descriptions .....	18
Table 4 – Progress with recommendations in 2012.....	19
Table 5 – Status of recommendations by year .....	19

---

## 1 Background

In April 2004, the European Parliament passed 'Directive 2004/49/EC of the European Parliament and of the Council of 29 April 2004 on safety on the Community's railways and amending Council Directive 95/18/EC on the licensing of railway undertakings and Directive 2001/14/EC on the allocation of railway infrastructure capacity and the levying of charges for the use of railway infrastructure and safety certification'. This directive is referred to as the Railway Safety Directive and set out the requirement for each European Union member state to establish a National Safety Authority (NSA) to oversee the regulation of railway safety and a National Investigation Body (NIB) to act as an independent accident investigation body.


The Railway Safety Act 2005 was passed on the 23<sup>rd</sup> December 2005, transposing the Railway Safety Directive into national legislation and creating the framework for the establishment of the Railway Safety Commission (RSC). On the 1<sup>st</sup> January 2006 the RSC was established transferring the regulation of railway safety from the then Department of Transport. The Railway Safety Act 2005 established the RSC to act as the NSA and perform the duties outlined in the Railway Safety Directive associated with the licensing of railways. The Railway Accident Investigation Unit (RAIU) was established as a functionally independent unit within the RSC to act as the NIB, independently investigating railway occurrences. The roles of the RSC and the RAIU were subsequently elaborated upon under the European Communities (Railway Safety) Regulations 2008, Statutory Instrument number 61 of 2008 (SI no. 61 of 2008) dated the 6<sup>th</sup> March 2008.

The purpose of an investigation by the RAIU is to improve railway safety by establishing, in so far as possible, the cause or causes of an accident or incident with a view to making safety recommendations for the avoidance of accidents in the future, or otherwise for the improvement of railway safety. It is not the purpose of an investigation to attribute blame or liability. The RAIU's investigations are carried out in accordance with the Railway Safety Act 2005 as amended by SI no. 61 of 2008 and the European Railway Safety Directive.

## 2 RAIU

### 2.1 The organisation

The RAIU comprises a Chief Investigator and a team of three investigators, each with the ability to perform the role of Investigator In Charge as necessary. One of the Senior Investigator positions became vacant in October 2012. The RAIU shares administrative support with the RSC, all other functions are carried out independently of the RSC. The organisation chart for the RSC, including the RAIU, is shown in Figure 1.



**Figure 1 – Organisation chart**

Regulations are currently being drafted to establish the RAIU as an independent unit within the Department of Transport, Tourism and Sport, giving them total independence from the regulatory body.

### 2.2 Railway networks within the RAIU's remit

There are ten railway systems within the RAIU's remit. These are:

- The Iarnród Éireann (IÉ) national heavy rail network;
- The Luas light rail system in Dublin;
- The Bord Na Móna industrial railway;
- Seven heritage railway systems.

---

For each of these railway systems there are entities identified as Railway Undertaking and Infrastructure Managers. Railway Undertakings are defined as organisations that provide the transport of goods and/or passengers by rail on the basis that the undertaking must ensure traction, including undertakings that provide traction only; which operate under a safety management system approved by the RSC through the issue of a safety certificate. Infrastructure Managers are defined as organisations that establish and maintain railway infrastructure, including the management of infrastructure control and safety systems; which operate under a safety management system approved by the RSC through the issue of a safety authorisation. There are ten organisations that act as Railway Undertaking and Infrastructure Manager for a railway network and two organisations that act solely as Railway Undertakings; there are currently no organisations that act solely as an Infrastructure Manager.

The national heavy rail system is owned by IÉ. IÉ are the Infrastructure Manager and are also the primary Railway Undertaking with responsibility for the management of commercial train operations, station operations and Centralised Traffic Control. The heavy rail system is interoperable with the heavy rail system in Northern Ireland and cross border services are operated by IÉ in conjunction with Translink, the Railway Undertaking in Northern Ireland. These operations are carried out under IÉ's Safety Case and Translink is classified as a guest operator. A heritage Railway Undertaking, the Railway Preservation Society of Ireland, also operates steam trains on the heavy rail system several times a year. The performance of the national heavy rail system is reported to the European Railway Agency (ERA) in accordance with European reporting requirements.

The Luas light rail system is owned by the Railway Procurement Agency. Transdev Transport is the Railway Undertaking that operates passenger services, the passenger stops and the Central Control Room. Transdev is also the Infrastructure Manager responsible for the maintenance of the infrastructure.

The Bord Na Móna industrial railway is owned and operated by Bord Na Móna, acting as the Railway Undertaking and Infrastructure Manager for the transport of peat on its network. As this is an industrial railway and does not carry passengers it only falls within the RAIU's remit where the railway interfaces with the public, such as at level crossings and bridges.

The operational heritage railway systems in 2013 included: Cavan and Leitrim Railway; Diffin Railway; Fintown Railway; Irish Steam Preservation Society; Lartigue Monorailway; Waterford and Suir Valley Railway; and West Clare Railway. Each of these acts as the Railway Undertaking and Infrastructure Manager for their system.

---

### **2.3 Non-investigative activities**

As part of its role as an NIB, the RAIU actively participates in the development of accident investigation processes and procedures through the work of ERA. To this end, the RAIU participated in the 2013 NIB plenary meetings and provided input on the direction of NIB related work. RAIU is also a member of the ERA taskforce set up to develop a system of cross auditing for the NIBs.

The RAIU attended the International Railway Safety Conference, as part of this event, continued to engage with NIBs from other countries by chairing the NIB Stakeholders meetings.

The Memorandums of Understanding entered into with the Transportation Safety Board of Canada and the Rail Accident Investigation Board of the United Kingdom of Great Britain and Northern Ireland remain in place. In 2013 a Memorandum of Understanding was established with the Health and Safety Authority. The also RAIU continued to work towards the possibility of further Memorandums of Understandings with, An Garda Síochána and the Coroner's Society of Ireland.

---

## 3 Occurrences

### 3.1 Classification of occurrences

Occurrences fall into one of three types as defined in Statutory Instrument (SI) no. 61 of 2008:

- Accident – An unwanted or unintended sudden event or a specific chain of such events which have harmful consequences including collisions, derailments, level crossing accidents, accidents to persons caused by rolling stock in motion, fires and others;
- Serious accident – Any train collision or derailment of trains, resulting in the death of at least one person or serious injuries to five or more persons or extensive damage to rolling stock, the infrastructure or the environment, and any other similar accident with an obvious impact on railway safety regulation or the management of safety, where extensive damage means damage that can be immediately assessed by the RAIU to cost at least €2,000,000 in total;
- Incident – Any occurrence, other than an accident or serious accident, associated with the operation of trains and affecting the safety of operation.

For clarity the meaning of the following terms should be noted:

- Harmful consequences – Injury to persons and/or damage to equipment;
- Serious injury – Any injury requiring hospitalisation for over 24 hours.

### 3.2 Investigation of occurrences

The RAIU have investigators on call, 24 hours a day, 7 days a week, who are notified of reportable occurrences by the Railway Undertakings in accordance with the Railway Safety Act 2005. Based on the nature of the occurrence and the legal requirements, a decision is made on whether or not an investigation is required. In accordance with the Railway Safety Directive, the RAIU must investigate serious accidents; accidents and incidents are investigated depending on the potential for safety lessons to be learnt.

Where notified occurrences warrant further investigation to determine whether or not an investigation is warranted a preliminary examination is carried out and one of the following four determinations is made:

- No further investigation – no safety improvements are likely to be identified that could have prevented the occurrence or otherwise improve railway safety;
- Trend investigation – where the occurrence is part of a group of related occurrences that may or may not have warranted an investigation as individual occurrences, but the apparent trend warrants investigation;

- Full investigation – there is clear evidence that the occurrence could have been prevented or the severity of the outcome could have been mitigated through the actions of those parties involved either directly or indirectly in the installation, operation and maintenance of the railway.

Investigations are classified as one of three types under the Railway Safety Directive:

- Article 19(1) – Investigations into serious accidents on the IÉ network, the objective of which is possible improvement of railway safety and the prevention of accidents;
- Article 19(2) – Investigation into accidents and incidents, which under slightly different conditions might have led to serious accidents on the IÉ network;
- Article 21(6) – Investigations into railway accidents and incidents under national legislation, this includes all investigations relating to the Luas light rail system, the Bord Na Móna industrial railway and the heritage railways.

For each investigation, the level of damage to rolling stock, track, other installations or environment is identified and classified based on the European common safety indicators as follows:

- None;
- Less than €150,000 (<€150,000);
- Equal to or greater than €150,000 (≥€150,000);
- Equal to or greater than €2,000,000 (≥€2,000,000).

Within seven days of a decision to carry out a full investigation, the RAIU advise the relevant railway undertaking of the decision. In accordance with SI no. 61 of 2008, the RAIU also notify the ERA within seven days of a decision to carry out a full investigation into an occurrence on the IÉ network.

The RSC, An Garda Síochána, the Health and Safety Authority and other organisations may carry out investigations in parallel with an RAIU investigation. The RAIU will share its own technical information with these Investigation Bodies, however, the investigations are carried out independently. Based on its investigation, the RAIU produce a report that is provided to all relevant parties, including the Railway Undertaking, the RSC and the Department of Transport, Tourism and Sport. Reports relating to the IÉ network are also provided to ERA. All investigation reports are made available in the public domain once they have been published.

In accordance with the Railway Safety Act 2005, for all occurrences notified to the RAIU the relevant railway must carry out an investigation and produce a report within six months.

### 3.3 Summary of occurrences in 2013

There were forty one preliminary examinations carried out in 2013. These are broken down into serious accidents, accidents and incidents, by network, in Table 1. From the preliminary examination reports produced, six full investigations were commenced; these are detailed in section 4.

**Table 1 – Preliminary examination reports in 2013 by network**

<b>Railway Network</b>	<b>Serious Accidents</b>	<b>Accidents</b>	<b>Incidents</b>
IÉ	6	14	11
Luas	1	9	0
Heritage railways	0	0	0
Bord Na Móna	0	0	0
<b>Total</b>	<b>7</b>	<b>23</b>	<b>11</b>

### 3.4 Investigations within the past five years

Table 2 shows the areas that have been examined through the RAIU investigations by occurrence type over the past five years. The occurrences are presented for all railways and for the IÉ network only. It should be noted that five of these occurrences that were investigated in 2012 were part of a trend investigation and therefore addressed in a single report. Table 2 also shows the RAIU's investigations by type for 2013 and for the past five years. Occurrences at level crossings and derailments remain the main focus of RAIU's investigations over the last five years.

**Table 2 – Full investigations within the past five years by type**

Occurrence		Year					5 year average	
Type	Subset	2009	2010	2011	2012	2013	Total	%
Serious accident	Serious Accident - Collisions	0	0	0	0	0	0	0.00
	Serious Accident - Derailments	0	0	0	0	0	0	0.00
	Serious Accident - Level crossing	0	2	0	0	0	2	6.45
	Serious Accident - To persons due to rolling stock in motion	0	0	0	0	0	0	0.00
	Serious Accident - Fires	0	0	0	0	0	0	0.00
	Serious Accident - Others	1	0	0	0	0	1	3.23
Accident	Accident - Collisions	3	0	1	0	0	4	12.90
	Accident - Derailments	2	2	0	1	0	5	16.13
	Accident - Level crossing	0	2	1	1	0	4	12.90
	Accident - To persons due to rolling stock in motion	0	0	0	0	0	0	0.00
	Accident - Fires	0	0	0	0	1	1	3.23
	Accident - Others	0	1	1	1	2	5	16.13
Incident	Incident - Infrastructure	0	0	0	0	0	0	0.00
	Incident - Energy	0	0	0	0	0	0	0.00
	Incident - Control-command & signalling	0	0	0	0	1	1	3.23
	Incident - Rolling stock	0	0	0	0	1	1	3.23
	Incident - Traffic operation & management	1	0	0	0	2	3	9.68
	Incident - Others	0	0	0	4	0	4	12.90
<b>Annual Total</b>		<b>7</b>	<b>7</b>	<b>3</b>	<b>7</b>	<b>7</b>	<b>31</b>	<b>100</b>




Figure 2 – Investigation trend 2009-2013

## 4 Investigations commenced in 2013

### 4.1 Irregularity during Single Line Working between Dundalk and Newry

On Friday, 22<sup>nd</sup> March 2013 weather conditions between Dundalk and Newry were such that there was a heavy downfall of snow and localised flooding in the area, causing landslips. This resulted in degraded conditions on the railway line running cross-border between the Republic of Ireland and Northern Ireland. Single Line Working (SLW) with a Pilotman was introduced over the Down Line, between Dundalk and Newry, to keep the rail services operational.

On the morning of Saturday 23<sup>rd</sup> March 2013, the Down Line remained clear for rail traffic and SLW was reintroduced between Newry and Dundalk. During the SLW operation two trains were allowed to travel from Dundalk to Newry in the same SLW section.



**Figure 3 – Rolling stock used for cross border service on 23<sup>rd</sup> March**

**Occurrence classification:**

Incident

**Subset:**

Traffic operation and management

**Investigation classification:**

Article 19(2)

**Fatalities and injuries:**

None

**Damage:**

None

### 4.2 Dart wrongside door failure at Salthill and Monkstown

At approximately 08:50 hours (hrs) on Saturday 10<sup>th</sup> August 2013, the DART service from Howth to Greystones was stopped at Salthill & Monkstown DART Station. When the driver had observed that all passengers had alighted and boarded the train, the driver pressed the 'door close' button. The driver noticed that the door interlocking light was illuminated, a light used by drivers for confirmation that the doors are closed. However, as the driver was about to take power, he looked back along the train, and he saw that the exterior amber lights were illuminated, indicating that the doors were open, and in the process of closing, which is contravention with the driver's guidelines and it not a failsafe mechanism which may have resulted to injuries to passengers. On inspection of the train, one of the autocouplers was found to be damaged, and although mechanically coupled the coupler was not electrically coupled.



Figure 4 Damaged to autocoupler

**Occurrence classification:**

Incident

**Subset:**

Rolling stock

**Investigation classification:**

Article 19(2)

**Fatalities and injuries:**

None

**Damage:**

None

### 4.3 Tram fire on approach to Busarás

On Thursday, 7<sup>th</sup> November 2013 at approximately 14:30 hours a Luas tram, operating on the Red Line Service, travelling from The Point to Tallaght experienced a failure resulting in significant fire protruding from the right side of the tram for a short period of time at the junction of Amiens Street and Store Street.



Figure 5 Fire on LUAS tram

Occurrence classification:

Accident

**Subset:**

Fires

**Investigation classification:**

Article 19(2)

**Fatalities and injuries:**

None

**Damage:**

None

### 4.4 Collapse of canopy at Cork Kent Station

On Thursday 18<sup>th</sup> November 2013 at approximately 15:01 hours the canopy covering platforms one and two at Cork Kent station collapsed. The canopy structure comprised of a timber roof supported by seventeen cast iron columns.



Figure 6 Debris on train at Cork station

**Occurrence classification:**

Accident

**Subset:**

Others

**Investigation classification:**

Article 19(1)

**Fatalities and injuries:**

One person on the platform was injured.

**Damage:**

≥€150,000

#### 4.5 Rockfall at Waterford station

On Tuesday 31<sup>st</sup> December 2013 at approximately 20:10 hours a large amount of rock fell from a IÉ cutting at Waterford Station. The debris occupied two lines at the station and fell close to base of the elevated signalling cabin structure. There were no trains operational at the time of the incident, with no reported injuries to staff.



Figure 7 Landslide obstructing track

**Occurrence classification:**

Accident

**Subset:**

Others

**Investigation classification:**

Article 19(2)

**Fatalities and injuries:**

None

**Damage:**

≥€150,000

#### 4.6 Signal Passed at Danger (SPAD) occurrences on IÉ network

**Occurrence 1:**

At approximately 13:13 hrs, on the 8th December 2013, the A303 Train (11.50 hrs passenger service from Tralee to Heuston) passed signal TL223 at danger while the A304 Train (12.10hrs passenger service from Cork to Tralee) was approaching the same platform at Millstreet. Both drivers brought their trains to a stop approximately 175 Metres apart on the platform in Millstreet Station.

---

**Occurrence 2:**

At approximately 07:04 hrs on the 19th December 2013, the 05:52 hrs service from Limerick to Galway, passed signal XE098DS at danger, and travelled through level crossing XE098 Gortavogher, while the gates were raised and open for to approaching road traffic. There had been multiple power system failures with the infrastructure in the area due to lightning strikes, which resulted in signal XE098DS not functioning; signals with no illuminated should always be considered by drivers to be at danger.

One trend investigation is to be conducted by the RAIU to include all relevant SPAD incidents.

## 5 Investigation reports published in 2013

### 5.1 Overview of investigation reports for 2013

The RAIU published three investigation reports in 2013. These related to: one level crossing accident, one locomotive runaway and one equipment failure on a train. A total of thirteen new safety recommendations were made.

### 5.2 Tram collision with a bus on O'Connell Street



**Figure 8 Tram collision with bus**

On Wednesday the 16<sup>th</sup> of September at approximately 14:55 hours a Luas tram, operating on the Red Line Service, travelling from Tallaght to Dublin Connolly collided with a Dublin Bus at the junction of O'Connell Street and Abbey Street. Twenty-one people, including the driver of the tram, were injured as a result of the collision; three of which sustained serious injuries.

Tram 3002 proceeded through a stop signal at the junction of Abbey Street and O'Connell

Street as a bus crossed through the junction on a green traffic signal which resulted in a collision.

The immediate cause of this collision was as a result of a lapse in concentration by the tram driver. There were no contributory or underlying factors identified in this report and no safety recommendations were made as a result of this accident.

### 5.3 Explosion on Dart at Bray Station



**Figure 9 Damage to driver bag and cabin**

On the 6<sup>th</sup> March 2012 the 08:00 hours DART service from Greystones to Malahide was stationary at Platform 2, Bray Railway Station awaiting a driver change over. The relief driver entered the driving cab at 08:10 hours, intending to drive the DART to Malahide

As the driver put his bag on the floor of the driving cab, eleven of the twelve railway fog signals that he was carrying in the bag exploded.

---

The driver sustained injuries to his hand and suffered some temporary loss of hearing. The interior of the cab was superficially damaged.

During the investigation it was found that the fog signal supplier had changed the fog signals supplied to Iarnród Éireann to a less robust fog signal. Iarnród Éireann had not been notified of this change and had not noticed the difference in fog signals until after the accident.

Although the immediate cause of the explosion of the fog signals could not be ascertained, the RAIU identified the following causal, contributory and underlying factors.

Causal to the explosion were the following causal factors:

- The Alsetex fog signals supplied to Iarnród Éireann, by Lacroix, were not as robust as the Lacroix fog signals requested by Iarnród Éireann;
- Iarnród Éireann did not notice that the Alsetex fog signals provided to them were not the Lacroix fog signals that were ordered.

The contributory factor identified was:

- The fog signals storage tube, designed by Iarnród Éireann, allowed the fog signals to impact on one another which may have caused them to degrade over time;

The underlying factors identified were:

- Iarnród Éireann did not risk assess the storage and transportation of fog signals outside of Central Stores;
- Iarnród Éireann had not introduced any training to staff in the handling of fog signals;
- Iarnród Éireann did not have a process in place for the checking of parts when they arrive at Central Stores.

The RAIU made three new safety recommendations, related to the occurrence, as follows:

- Iarnród Éireann should ensure that their procurement and quality control processes verify that goods received are of the correct specification as those ordered;
- Iarnród Éireann should introduce appropriate procedures and standards for the safe issue, storage and transportation of fog signals;
- Iarnród Éireann drivers should receive adequate training in the safe handling of fog signals.

#### 5.4 Tractor struck train at level crossing XE020



**Figure 10 Damage to tractor**

On the 20<sup>th</sup> June 2012 at 14:50 hours the 14:15 hour's passenger train travelling from Limerick to Galway was involved in a collision with a tractor at level crossing number XE020 which is located close to Cratloe, County Clare on the R462. The driver of the train was initially unaware of the collision and continued to Sixmilebridge Station. The tractor driver although shocked was uninjured and the tractor sustained frontal damage.

The immediate cause of the accident was that that tractor entered the swept path of the train as the train was travelling through the level crossing.

The contributory factors identified were:

- The viewing distances failed to meet the requirements set out in of Iarnród Éireann's CCE-TMS-380, Technical Standard for the Management of User Worked Level Crossings;
- The Tractor Driver had to position the tractor within the swept path of the train in order to look for trains;
- The Tractor Driver had been using the railway signals to estimate train approaching times, a system which may have been adopted due to the poor viewing distances at the level crossing but contradicts the instructions given in the Safe Use of Level Crossings guidance booklet.

The underlying factors identified were:

- Having been unable to close the level crossing due to a lack of agreement between the relevant land owners, Iarnród Éireann did not introduce adequate safety measures as a result of the inadequate viewing distances at the level crossing;
- Iarnród Éireann may not have prioritised work at this level crossing as a result of the low risk rankings awarded by Iarnród Éireann's Level Crossing Risk Model.

---

The following additional observation, not relating to the cause of the accident, was made during the investigation:

- The signalman did not have the sufficient information immediately available to him to assist the Emergency Services to respond to the accident scene.

The RAIU made three new safety recommendations, related to the occurrence, as follows:

- Iarnród Éireann should close, move or alter the level crossing in order to meet the required viewing distances in Iarnród Éireann's technical standard CCE-TMS-380 Technical Standard for the Management of User Worked Level Crossings;
- Iarnród Éireann should review their systems of managing level crossings that fail to meet the viewing distances in Iarnród Éireann technical standard CCE-TMS 380 Technical Standard for the Management of User Worked Level Crossings to ensure that any mitigation measure that is introduced is effective at reducing the risk to level crossing users;
- Iarnród Éireann should audit their Level Crossing Risk Model, to ensure it correctly identifies high risk level crossings; and identifies appropriate risk mitigation measures for individual level crossings.

One new safety recommendation was made as a result of an additional observation:

- IÉ staff who may be required to contact the emergency services should have the appropriate information readily available to them in order to give clear instructions to the emergency services in order that they can attend accident sites in a prompt manner. This information should then be updated in IÉ Rule Book.

One previous RAIU safety recommendation was re-iterated as a result of this investigation.

- IÉ should review their procedures for the management of accidents to ensure that communication with the emergency services is clear and provides the necessary information to locate an accident without undue delay and access it by the most appropriate point.

## 6 Safety recommendations

### 6.1 Monitoring of RAIU safety recommendations

Under the Railway Safety Act 2005, the RSC is responsible for monitoring the implementation of RAIU recommendations. All safety recommendations issued by RAIU are addressed to the RSC unless otherwise stated and the implementers are identified in the recommendation. The recommendations issued by the RAIU are reviewed by RSC for acceptability and where RSC accept the recommendations it monitors their implementation. Table 3 identifies the three status codes assigned to recommendations by RSC and the definition of each.

**Table 3 – Recommendation status descriptions**

Status	Description
Open	Feedback from implementer is awaited or actions have not yet been completed.
Complete	Implementer has taken measures to effect the recommendation and the RSC is considering whether to close the recommendation.
Closed	Implementer has taken measures to effect the recommendation and the RSC has considered these and has closed the recommendation.

Open recommendations are those for which RSC has received some or no update from the organisation or organisations responsible for implementing the recommendation and for which further action is deemed to be required by RSC. This status is assigned by RSC.

Complete recommendations are those where the organisation responsible for implementing the recommendation is satisfied that it has carried out the necessary actions to address the recommendation and for which RSC has received evidence of implementation that it will review to determine whether or not the recommendation is closed. This status is advised to RSC by the organisation or organisations responsible for implementing the recommendation.

Closed recommendations are those for which RSC is satisfied that the organisation responsible for implementing the recommendation has taken suitable action to address the recommendation. This status is assigned by RSC.

### 6.2 Progress in 2013

The progress with the implementation of recommendations in 2013 is shown in Table 4. The status of forty six recommendations did not change in 2013, of which seven were issued in 2013. The status of five recommendations was upgraded from open to complete. The status of eight recommendations was upgraded from complete to close. The status of six recommendations was upgraded from open to close.

**Table 4 – Progress with recommendations in 2012**

Status	End 2012	New in 2013	End 2013
Open	29	7	27
Complete	29	0	24
Closed	32	0	46
Total	90	7	97

The RSC as the NSA for Ireland holds meetings with the relevant stakeholders to monitor the progress of recommendations. An update is included in the Appendix on the status of individual recommendations that were not closed prior to 2013 and the recommendations are listed in chronological order by investigation report. For clarity and completeness a comment has been included on the status of individual recommendations.

### 6.3 Summary of status of recommendations


As of the 31<sup>st</sup> December 2013, the RAIU have made 97 recommendations. In addition to these the RAIU have included the 14 recommendations made by RSC in its investigation report published in 2006 on the collapse of the Cahir viaduct in 2003. All recommendations were accepted by their addressee and implementer. The status of the recommendations as of the end of 2013 is included in Table 5.

**Table 5 – Status of recommendations by year**

Year	Recommendations	Accepted by implementer	Open		Complete		Closed	
			No.	%	No.	%	No.	%
2006	14*	14	1	7.14	3	21.43	10	71.43
2007	-	-	-	-	-	-	-	-
2008	7	7	1	14.29	2	28.57	4	57.14
2009	13	13	0	0.00	1	07.69	12	92.31
2010	26	26	6	23.08	4	15.38	16	61.54
2011	17	17	6	35.29	9	52.94	2	11.76
2012	13	13	6	46.15	5	38.46	2	15.38
2013	7	7	7	100.00	0	0.00	0	0.00
<b>Total</b>	<b>97</b>	<b>97</b>	<b>27</b>		<b>24</b>		<b>46</b>	

\*Recommendations issued by the RSC

The overall progress with the closure of recommendations is shown in Figure 11. Forty-seven percent recommendations issued have been closed and a quarter are at the stage where the organisation responsible for implementing them believes they have been fully addressed and therefore complete.



**Figure 11 – Status of recommendations**

## Appendix – Status of individual recommendations by report – 2006

Investigation report no.	None	Issued	July 2006
<b>Inquiry into the Derailment of a Freight Train at Cahir Viaduct on 7<sup>th</sup> October 2003</b>			
<b>Recommendations</b>			<b>Total no. 14</b>
2006-001	<p>IÉ should conduct a review of its safety management system to identify all areas where design, inspection and maintenance procedures are not fully developed and documented, and should establish a programme to develop and implement the necessary specifications and standards prioritised on the basis of safety risk. The content and structure of each specification or standard should reflect the safety criticality of the various elements of the associated procedure or physical asset.</p>		
<b>Comment</b>	No change of status in 2013.		<b>Status</b>
			<b>Complete</b>
2006-003	<p>IÉ should review the derailment containment arrangements on its various structures and make whatever modifications might be required to ensure that they are fit for purpose and capable of preventing disproportionate failure.</p>		
<b>Comment</b>	No change of status in 2013.		<b>Status</b>
			<b>Open</b>
2006-009	<p>IÉ should ensure that, pending full implementation and validation of new data management systems including those currently in course of development, comprehensive and up to date records of infrastructure asset inspection and maintenance are maintained and that relevant data is effectively promulgated to inspectors, maintainers and managers.</p>		
<b>Comment</b>	No change of status in 2013.		<b>Status</b>
			<b>Complete</b>
2006-015	<p>IÉ should review its existing communications systems and take whatever action is necessary to ensure that on all parts of system train drivers are provided with an effective means of communication with the controlling signalman.</p>		
<b>Comment</b>	No change of status in 2013. Note: Recommendation 2006-014 does not exist.		<b>Status</b>
			<b>Complete</b>

## Status of individual recommendations by report – 2008

<b>Investigation report no.</b>	07062801	<b>Issued</b>	18 <sup>th</sup> June 2008
<b>Report into the Collision at Level Crossing XN 104 between Ballybrophy and Killonan on the 28th of June, 2007</b>			
<b>Recommendations</b>			<b>Total no.</b> 7
2008-001	<p>IÉ to review the various sources of information relevant to level crossings and develop a standard, or suite of standards, consolidating information on: civil engineering specifications; signage specifications; visibility of approaching trains; and inspection and maintenance. Ensuring effective implementation and compliance</p>		
<b>Comment</b>	No change of status in 2013.		<b>Status</b>
			Complete
2008-003	<p>IÉ to develop and implement a vegetation management programme that addresses vegetation management on a risk basis, prioritising high risk areas.</p>		
<b>Comment</b>	No change of status in 2013.		<b>Status</b>
			Complete
2008-004	<p>IÉ to ensure that a system is put in place for effective implementation of existing standards and to manage the timely introduction of new and revised standards, this should include departmental instructions.</p>		
<b>Comment</b>	No change of status in 2013.		<b>Status</b>
			Open

## Status of individual recommendations by report – 2009

Investigation report no.		08022801	Issued	2 <sup>nd</sup> March 2009
<b>Report into the Fatality at Level Crossing XX 032 between Ballina and Manulla Junction on the 28th of February 2008</b>				
<b>Recommendations</b>				<b>Total no.</b> 4
2009-002	IÉ should, taking into account the close proximity of the three level crossings, close or upgrade some or all of these crossings.			
	<b>Comment</b>	Status upgraded from open to closed in 2013.		<b>Status</b> Closed
2009-003	IÉ must identify crossings that are regularly misused and take proactive action to manage the increased risk created by this misuse.			
	<b>Comment</b>	No change of status in 2013.		<b>Status</b> Complete

Investigation report no.		08073101	Issued	29 <sup>th</sup> July 2009
<b>Collision between a train and a road vehicle at level crossing XN125, Cappadine, on the Ballybrophy to Killonan line 31st of July 2008</b>				
<b>Recommendations</b>				<b>Total no.</b> 2
2009-009	IÉ should assess the risks relating to road users' behaviour in identifying a safe stopping position at User Worked Level Crossings and based on the outcome of this risk assessment, IÉ should introduce measures to allow safe use of this type of level crossing. This recommendation was reiterated by RAIU in 2011 as part of investigation report 2011-007.			
	<b>Comment</b>	Status upgraded from complete to closed in 2013.		<b>Status</b> Closed
2009-010	IÉ should carry out risk assessments on level crossings that fail to meet the viewing distances specified in the RSC guidance and implement appropriate measures in order to meet this guidance as a minimum.			
	<b>Comment</b>	Status upgraded from complete to closed in 2013.		<b>Status</b> Closed

## Status of individual recommendations by report - 2010

<b>Investigation report no.</b>	R2010-003	<b>Issued</b>	10 <sup>th</sup> June 2010
<b>Derailment of an on track machine at Limerick Junction Station on the Dublin to Cork Line, 3rd of July 2009</b>			
<b>Time &amp; Date</b>	04:50, 3 <sup>rd</sup> July 2009	<b>Location</b>	Limerick Junction Station
<b>Railway</b>	IÉ	<b>Line</b>	Dublin to Cork line
<b>Recommendations</b>			<b>Total no.</b> 2
2010-003	IÉ should put in place a formalised process to ensure that life expired points are removed from service, where this is not possible a risk assessment should be carried out and appropriate controls should be implemented to manage the risks identified.		
	<b>Comment</b>	No change of status in 2013.	<b>Status</b>
			Complete

<b>Investigation report no.</b>	2010-R004	<b>Issued</b>	16 <sup>th</sup> August 2010
<b>Malahide Viaduct Collapse on the Dublin to Belfast Line, on the 21st August 2009</b>			
<b>Time &amp; Date</b>	18:20, 21 <sup>st</sup> August 2009	<b>Location</b>	Malahide viaduct
<b>Railway</b>	IÉ	<b>Line</b>	Dublin to Belfast line
<b>Recommendations</b>			<b>Total no.</b> 15
2010-008	IÉ should introduce a verification process to ensure that all requirements of their Structural Inspections Standard, I-STR-6510, are carried out in full.		
	<b>Comment</b>	Status upgraded from complete to closed in 2013.	<b>Status</b>
			Closed
2010-009	IÉ should ensure that a system is put in place for effective implementation of existing standards and to manage the timely introduction of new and revised standards.		
	<b>Comment</b>	Status upgraded from open to closed in 2013.	<b>Status</b>
			Closed
2010-011	IÉ should carry out inspections for all bridges subject to the passage of water for their vulnerability to scour, and where possible identify the bridge foundations. A risk-based management system should then be adopted for the routine examination of these vulnerable structures.		
	<b>Comment</b>	Status upgraded from open to closed in 2013.	<b>Status</b>
			Closed

2010-012	<p>IÉ should develop a documented risk-based approach for flood and scour risk to railway structures through:</p> <ul style="list-style-type: none"> <li>Monitoring of scour risk at sites through scour depth estimation, debris and hydraulic loading checks, and visual and underwater examination;</li> <li>Provision of physical scour / flood protection for structures at high risk;</li> <li>Imposing of line closures during periods of high water levels where effective physical protection is not in place.</li> </ul>	
<b>Comment</b>	Status upgraded from complete to closed in 2013.	<b>Status</b> Closed
2010-013	<p>IÉ should adopt a formal process for conducting structural inspections in the case of a report of a structural defect from a member of the public.</p>	
<b>Comment</b>	No change of status in 2013.	<b>Status</b> Complete
2010-014	<p>IÉ should introduce a training, assessment and competency management system in relation to the training of structural inspectors, which includes a mentoring scheme for engineers to gain the appropriate training and experience required to carry out inspections.</p>	
<b>Comment</b>	Status upgraded from complete to closed in 2013.	<b>Status</b> Closed
2010-015	<p>IÉ should review their network for historic maintenance regimes and record this information in their information asset management system. For any future maintenance regimes introduced on the network, IÉ should also record this information in their information asset management system.</p>	
<b>Comment</b>	No change of status in 2013. The project to implement this recommendation is in progress.	<b>Status</b> Open
2010-017	<p>IÉ should carry out an audit of their filed and archived documents, in relation to structural assets, and input this information into their information asset management system.</p>	
<b>Comment</b>	No change of status in 2013. Archiving of bridge data is taking place.	<b>Status</b> Open
2010-018	<p>The RSC should review their process for the closing of recommendations made to IÉ by independent bodies, ensuring that they have the required evidence to close these recommendations. Based on this process the RSC should also confirm that all previously closed recommendations satisfy this new process.</p>	
<b>Comment</b>	No change of status in 2013. RSC has reviewed and updated its procedures for the management of safety recommendations; these were published in the first quarter of 2012. A review of the safety recommendations issued by AD little and IRMS is taking place.	<b>Status</b> Open

2010-019	The RSC, in conjunction with IÉ, should develop an action plan in order to close all outstanding recommendations in the AD Little Review (2006) and the International Risk Management Services Reviews (1998, 2000, 2001). This action plan should include defined timescales for the implementation and closure of all these recommendations.		
<b>Comment</b>	No change of status in 2013. A review of the safety recommendations issued by AD little and IRMS is taking place.	<b>Status</b>	Open

<b>Investigation report no.</b>	2010-R005	<b>Issued</b>	24 <sup>th</sup> August 2010
<b>Irregular operation of Automatic Half Barriers at Fern's Lock, County Kildare, on the Dublin to Sligo Line, 2<sup>nd</sup> September 2009</b>			
<b>Occurrence date</b>	2 <sup>nd</sup> September 2009	<b>Location</b>	Level crossing XG019
<b>Railway</b>	IÉ	<b>Line</b>	Dublin to Sligo line
<b>Recommendations</b>		<b>Total no.</b>	1
2010-020	IÉ should review the competencies of all signalmen to ensure that when signalmen are assigned relief duties they have the required training and experience to perform these duties appropriately.		
<b>Comment</b>	No change of status in 2013.	<b>Status</b>	Open

<b>Investigation report no.</b>	2010-R006	<b>Issued</b>	15 <sup>th</sup> November 2010
<b>Derailment of empty train due to collision with landslip debris outside Wicklow Station, 16<sup>th</sup> of November 2009</b>			
<b>Occurrence date</b>	16 <sup>th</sup> November 2009	<b>Location</b>	28 ½ milepost
<b>Railway</b>	IÉ	<b>Line</b>	Dublin to Rosslare Europort
<b>Recommendations</b>		<b>Total no.</b>	6
2010-021	IÉ should review their vegetation management processes to ensure that vegetation covering substantial earthworks structures is adequately maintained to facilitate the monitoring and inspection of earthwork structures by patrol gangers and other inspection staff.		
<b>Comment</b>	Status upgraded from complete to closed in 2013.	<b>Status</b>	Closed
2010-022	IÉ should review the effectiveness of their standards in relation to conducting earthworks inspections during periods of heavy rainfall, ensuring that earthworks vulnerable to failure are inspected during these periods by appropriately trained patrol gangers or inspectors.		
<b>Comment</b>	Status upgraded from complete to closed in 2013.	<b>Status</b>	Closed

2010-024	<p>IÉ should review their structures list and ensure that all earthworks are identified and included on this list. Upon updating this list, a programme for the inspection of earthworks is to be developed and adopted at the frequency requirements set out by the Structural Inspections Standard, I-STR-6510.</p>	<p><b>Comment</b> No change of status in 2013. The project to implement this recommendation is in progress. <b>Status</b> Open</p>
2010-025	<p>IÉ and the RSC should review their process for the issuing of guidance documents, to ensure that the third parties affected by these guidance documents are made aware of their existence.</p>	<p><b>Comment</b> No change of status in 2013. <b>Status</b> Complete</p>
2010-026	<p>IÉ should review the effectiveness of their Structural Inspections Standard, I-STR-6510, with consideration for the possibility of more thorough inspections being carried out on cuttings to establish the topography and geotechnical properties of cuttings; and from this information identify any cuttings that are vulnerable to failure.</p>	<p><b>Comment</b> No change of status in 2013. <b>Status</b> Complete</p>

## Status of individual recommendations by report - 2011

<b>Investigation report no.</b>	2011-R001	<b>Issued</b>	19 <sup>th</sup> January 2011
<b>Laois Traincare Depot Derailment, 20<sup>th</sup> January 2010</b>			
<b>Occurrence date</b>	20 <sup>th</sup> January 2010	<b>Location</b>	Laois Traincare Depot
<b>Railway</b>	IÉ	<b>Line</b>	Dublin to Cork line
<b>Recommendations</b>		<b>Total no.</b>	2
2011-001	IÉ should ensure that the risks relating to use of spring assisted manual points are identified and that appropriate control measures are implemented based on the risks identified.		
	<b>Comment</b>	Status upgraded from open to closed in 2013.	<b>Status</b>
			Closed
2011-002	IÉ should ensure that the Signal Sighting Committee is informed when train drivers report difficulties viewing a signal and the Signal Sighting Committee should verify that the reported difficulties are addressed effectively.		
	<b>Comment</b>	No change of status in 2013.	<b>Status</b>
			Complete

<b>Investigation report no.</b>	2011-R002	<b>Issued</b>	5 <sup>th</sup> May 2011
<b>Secondary suspension failure on a train at Connolly Station, 7<sup>th</sup> May 2010</b>			
<b>Occurrence date</b>	7 <sup>th</sup> May 2010	<b>Location</b>	Connolly Station
<b>Railway</b>	IÉ	<b>Line</b>	Dublin to Sligo line
<b>Recommendations</b>		<b>Total no.</b>	3
2011-003	IÉ should ensure all work in rolling stock maintenance depots is carried out in accordance with its control process.		
	<b>Comment</b>	No change of status in 2013.	<b>Status</b>
			Complete
2011-004	IÉ should review its process of managing the hazard log in relation to the Class 29000s to ensure the adequacy of this process and verify that implementation of closure arguments in the hazard log is effective.		
	<b>Comment</b>	No change of status in 2013.	<b>Status</b>
			Open
2011-005	IÉ should evaluate the risks relating to failure of the centre pivot pin to perform its function due to over-inflation of the secondary suspension and determine if any design modifications are required to avoid future failures.		
	<b>Comment</b>	Status upgraded from open to complete in 2013.	<b>Status</b>
			Complete

<b>Investigation report no.</b>	2011-R003	<b>Issued</b>	11 <sup>th</sup> May 2011
<b>Tram derailment at The Point stop, Luas Red Line, 13<sup>th</sup> May 2010</b>			
<b>Occurrence date</b>	11 <sup>th</sup> May 2010	<b>Location</b>	The Point stop
<b>Railway</b>	IÉ	<b>Line</b>	Luas Red line
<b>Recommendations</b>			<b>Total no.</b> 1
2011-006	Veolia should introduce a communication protocol between normal and emergency for given situations where a clear understanding between a tram driver and Central Control Room are required.		
	<b>Comment</b>	No change of status in 2013.	<b>Status</b>
			Complete

<b>Investigation report no.</b>	2011-R004	<b>Issued</b>	27 <sup>th</sup> June 2011
<b>Gate Strike at Buttevant Level Crossing (XC 219), County Cork, on the 2<sup>nd</sup> July 2010</b>			
<b>Occurrence date</b>	2 <sup>nd</sup> July 2010	<b>Location</b>	Level crossing XC219
<b>Railway</b>	IÉ	<b>Line</b>	Dublin to Cork line
<b>Recommendations</b>			<b>Total no.</b> 2
2011-007	IÉ should identify similar manned level crossings where human error could result in the level crossing gates being opened to road traffic when a train is approaching; where such level crossings exist, IÉ should implement engineered safeguards; where appropriate.		
	<b>Comment</b>	No change of status in 2013.	<b>Status</b>
			Open
2011-008	IÉ should review its risk management process for manned level crossings to ensure that risks are appropriately identified, assessed and managed to ensure that existing level crossing equipment is compliant with criteria set out in IÉ's signalling standards, where appropriate.		
	<b>Comment</b>	Status upgraded from complete to closed in 2013.	<b>Status</b>
			Closed

<b>Investigation report no.</b>	2011-R005	<b>Issued</b>	18 <sup>th</sup> July 2011
<b>Person struck at level crossing XE039, County Clare, 27<sup>th</sup> June 2010</b>			
<b>Occurrence date</b>	27 <sup>th</sup> June 2010	<b>Location</b>	Level crossing XE039
<b>Railway</b>	IÉ	<b>Line</b>	Limerick to Claremorris line
<b>Recommendations</b>			<b>Total no.</b> 3
2011-009	IÉ should ensure that risk assessments are produced for all user worked level crossings to identify all hazards specific to particular level crossings.		
	<b>Comment</b>	No change of status in 2013.	<b>Status</b>
			Complete

2011-010	IÉ should review their documentation on the measurement of viewing distances at existing user worked level crossings to ensure that the viewing distances provide sufficient views of approaching trains to allow level crossing users cross safely.
<b>Comment</b>	No change of status in 2013.
2011-011	IÉ should review their procedures for the management of accidents to ensure that communication with the emergency services is clear and provides the necessary information to locate an accident site without undue delay and access it by the most appropriate point.
<b>Comment</b>	No change of status in 2013.
<b>Note</b>	Recommendation 2008-003 from investigation report 07062801 was reiterated.

<b>Investigation report no.</b>	2011-R006	<b>Issued</b>	4 <sup>th</sup> October 2011
<b>Road vehicle struck at level crossing XM096, County Roscommon, 2<sup>nd</sup> September 2010</b>			
<b>Occurrence date</b>	2 <sup>nd</sup> September 2010	<b>Location</b>	Level crossing XM096
<b>Railway</b>	IÉ	<b>Line</b>	Athlone to Westport line
<b>Recommendations</b>		<b>Total no.</b>	5
2011-012	IÉ should put in place a formal process for identifying and communicating with known users of user worked level crossings.		
<b>Comment</b>	No change of status in 2013.	<b>Status</b>	Open
2011-013	IÉ should review the effectiveness of its signage at user worked level crossings, and amend it where appropriate, taking into account the information provided in the level crossing user booklet. The review should include the information on the use of railway signals, what to do in case of difficulty when crossing the railway and ensuring the signage is illustrated in a clear and concise manner, taking into account current best practice and statutory requirements.		
<b>Comment</b>	No change of status in 2013.	<b>Status</b>	Open
2011-014	IÉ should update its risk management system to ensure that interim control measures are put in place where longer term controls to address risks require time to implement.		
<b>Comment</b>	No change of status in 2013.	<b>Status</b>	Open
2011-015	IÉ should review how it determines the safe crossing time for user worked level crossings to ensure the safe crossing time allows adequate time for movements and includes a safety margin, over and above the crossing time.		
<b>Comment</b>	Status upgraded from open to complete in 2013.	<b>Status</b>	Complete

2011-016	IÉ should review its use of disused rail as fencing at user worked level crossings to ensure it cannot potentially increase the severity of a collision and where this is the case, replace the disused rail with appropriate fencing.		
	Comment	No change of status in 2013.	Status
			Open
Note	Recommendation 2008-003 from investigation report 07062801 was reiterated.		

<b>Investigation report no.</b>	2011-R007	<b>Issued</b>	19 <sup>th</sup> October 2010
<b>Car Strike at Knockaphunta Level Crossing (XM250), County Mayo, 24<sup>th</sup> October 2010</b>			
<b>Occurrence date</b>	24 <sup>th</sup> October 2010	<b>Location</b>	Level crossing XM250
<b>Railway</b>	IÉ	<b>Line</b>	Athlone to Westport line
<b>Recommendations</b>		<b>Total no.</b>	1
2011-017	IÉ should upgrade the Level Crossing to ensure that the operation of the Level Crossing is not reliant on any direct action by the level crossing user.		
	Comment	Status upgraded from open to complete closed in 2013.	Status
			Complete
Note	Recommendation 2009-003 from investigation report 08022801 and recommendation 2009-009 from investigation report 08073101 were reiterated.		

## Status of individual recommendations by report – 2012

Investigation report no.	2012-R001	Issued	08 <sup>th</sup> February 2012
<b>Car Strike at Murrough Level Crossing XG 173, 14<sup>th</sup> February 2011</b>			
Occurrence date	14 <sup>th</sup> February 2011	Location	Level Crossing XG 173 (Morrough)
Railway	IÉ	Line	Dublin to Galway
Recommendations			Total no. 4
2012-001	IÉ should review the suitability of the signage at user worked crossings on public and private roads, ensuring that human factors issues are identified and addressed.		
	Comment	No change of status in 2013.	Status Open
2012-002	IÉ should liaise with local authorities where private road level crossings can be accessed from a public road to ensure there is advance warning to road users		
	Comment	No change of status in 2013.	Status Open
2012-003	IÉ should ensure that they adopt their own standards in relation to design changes to any PEIO that has the potential to affect safety.		
	Comment	No change of status in 2013.	Status Complete
2012-004	The RSC should ensure that they adopt a formal approach to submissions made by IÉ in relation to design changes to any PEIO that has the potential to affect safety.		
	Comment	Status upgraded from open to closed in 2013.	Status Closed

Investigation report no.	2012-R002	Issued	19 <sup>th</sup> September 2012
<b>Runaway locomotive at Portlaoise Loop, 29<sup>th</sup> November 2012</b>			
Occurrence date	29 <sup>th</sup> November 2011	Location	Portlaoise Loop
Railway	IÉ	Line	Dublin to Cork
Recommendations			Total no. 4
2012-005	IÉ should review their VMIs for locomotives to ensure that there are adequate braking tests at appropriate intervals.		
	Comment	No change of status in 2013.	Status Complete
2012-006	IÉ should adopt a quality control system, for the introduction of new maintenance procedures for locomotives.		
	Comment	No change of status in 2013.	Status Complete

2012-007	IÉ should review their system for introducing new train drivers' manuals, to ensure that train drivers are fully trained and assessed in all aspects of these manuals.	
	<b>Comment</b>	No change of status in 2013.
		<b>Status</b> Open
2012-008	IÉ should review their competency management system for train drivers to ensure that all driving tasks are routinely assessed.	
	<b>Comment</b>	No change of status in 2013.
		<b>Status</b> Open

<b>Investigation report no.</b>	2012-R003	<b>Issued</b>	26 <sup>th</sup> September 2012
<b>Bearing failure on a train at Connolly Station, 18<sup>th</sup> October 2012</b>			
<b>Occurrence date</b>	18 <sup>th</sup> October 2011	<b>Location</b>	Connolly Station
<b>Railway</b>	IÉ	<b>Line</b>	Dublin to Belfast
<b>Recommendations</b>		<b>Total no.</b>	5
2012-009	IÉ should put in place provisions to assist train drivers with the task of identifying if there is a fault present with an axlebox.		
	<b>Comment</b>	Status upgraded from open to closed in 2013.	
		<b>Status</b> Closed	
2012-010	IÉ should ensure the competency management system for signalmen includes the assessment of HABD related functions they perform.		
	<b>Comment</b>	No change of status in 2013.	
		<b>Status</b> Open	
2012-011	IÉ should put in place formal procedures governing the role of FTS staff in relation to HABDs.		
	<b>Comment</b>	Status upgraded from open to complete in 2013.	
		<b>Status</b> Complete	
2012-012	IÉ should ensure that a robust system is put in place for the competency assessment of safety critical rolling stock maintenance staff.		
	<b>Comment</b>	Status upgraded from open to complete in 2013.	
		<b>Status</b> Complete	
2012-013	IÉ should update its competency management system for train drivers to include assessment of their competency in relation to their tasks following a HABD alarm.		
	<b>Comment</b>	No change of status in 2013.	
		<b>Status</b> Open	

## Status of individual recommendations by report – 2013

<b>Investigation report no.</b>	2013-R002	<b>Issued</b>	17 <sup>th</sup> June 2013
<b>Tractor struck train at level crossing XE020, 20<sup>th</sup> June 2012</b>			
<b>Occurrence date</b>	14 <sup>th</sup> February 2011	<b>Location</b>	Level Crossing XE 020
<b>Railway</b>	IÉ	<b>Line</b>	Dublin to Galway
<b>Recommendations</b>		<b>Total no.</b>	4
2013-001	IÉ should close, move or alter the level crossing in order to meet the required viewing distances in IÉ's technical standard CCE-TMS-380 Technical Standard for the Management of User Worked Level Crossings.		
	<b>Comment</b>		<b>Status</b>
			Open
2013-002	IÉ should review their systems of managing level crossings that fail to meet the viewing distances in IÉ technical standard CCE-TMS 380 Technical Standard for the Management of User Worked Level Crossings to ensure that any mitigation measure that is introduced is effective at reducing the risk to level crossing users.		
	<b>Comment</b>		<b>Status</b>
			Open
2013-003	IÉ should audit their LCRM system, to ensure it correctly identifies high risk level crossings; and identifies appropriate risk mitigation measures for individual level crossings.		
	<b>Comment</b>		<b>Status</b>
			Open
2013-004	IÉ staff who may be required to contact the emergency services should have the appropriate information readily available to them in order to give clear instructions to the emergency services in order that they can attend accident sites in a prompt manner. This information should then be updated in IÉ's Rule Book.		
	<b>Comment</b>		<b>Status</b>
			Open
<b>Note</b>	Recommendation 2011-011 from investigation report 2011-R005 was reiterated.		

<b>Investigation report no.</b>	2013-R003	<b>Issued</b>	19 <sup>th</sup> September 2013
<b>Fog signal activation in Dart driving cab, Bray, on the 6th March 2012.</b>			
<b>Occurrence date</b>	6 <sup>th</sup> March 2012	<b>Location</b>	Bray train station
<b>Railway</b>	IÉ	<b>Line</b>	Dublin to Rosslare Europort
<b>Recommendations</b>			Total no. 4
2013-005	IÉ should ensure that their procurement and quality control processes verify that goods received are of the correct specification as those ordered.		
	<b>Comment</b>		<b>Status</b>
			Open
2013-006	IÉ should introduce appropriate procedures and standards for the safe issue, storage and transportation of fog signals.		
	<b>Comment</b>		<b>Status</b>
			Open
2013-007	IÉ drivers should receive adequate training in the safe handling of fog signals.		
	<b>Comment</b>		<b>Status</b>
			Open



2<sup>nd</sup> floor, 2 Leeson Lane

Dublin 2

Ireland

+353 1 6041242

[info@raiu.ie](mailto:info@raiu.ie)

[www.raiu.ie](http://www.raiu.ie)